



Add Note 1, "1. The brightness level of the potted assembly shall be a minimum of 95% of the brightness level of the unpotted lamp as specified on the lamp drawing."

SQ 1173745:

Page 1, PART I, add:

"ISO 10012-1  
Quality Assurance Requirements for Measuring Equipment  
Part I: Metrological Confirmation  
System for Measuring Rquipment

"ANSI/NCSL Z540-1  
General Requirements for Calibration Laboratories and  
Measuring and Test Equipment"

Page 4, at MAJOR 108, delete "and brightness decay" and change inspection method from 501" to "503".

at MAJOR 109, change inspection method from "502" to "501".

at MAJOR 110, change inspection method from "503" to "502".

Page 6, paragraph b, delete "the photometer will be calibrated on a six-month....prior to this testing". and substitute "The photometer shall be calibrated in accordance with ISO 10012-1 or ANSI/NCSL Z540-1

11750723: Add Distribution Statement "A"

TDPL:

DOCUMENT:	DELETE:	SUBSTITUTE:	ADD:
11785530	--	--	rev B
			Prefix Code DX
SPI 11733745	rev C	rev D	--
HCSDS 1932	rev G	rev H	--
ISO 10012-1	--	--	00/00/92
ANSI/NCSL Z540-1	--	--	00/00/94