

Lamp Brightness

The specified brightness data for the lamps being purchased is called out on the drawings referred to by the contract instrument.

1. The contractor shall furnish actual lamp brightness data of the lot received, and the date it was measured. This data shall be known as “initial lamp brightness data” and shall be obtained from the lamp vendor’s data prior to their shipment, or measured when the sources arrive at the assembly facility. The obtained data shall be recorded and maintained till the end process is completed.
2. Upon completion of assembly processes prior to shipment, and not less than 30 days from the initial brightness measurements, the contractor shall again measure actual lamp brightness, record the data and date it was measured. Lamp brightness measurements shall be within drawing specifications.
3. This end state data, the initial data, and final Wipe Test results required by the contract shall then be forwarded for approval via electronic means to AMSTA-AR-QAW-C, Bldg 62, 2nd Floor NW, Rock Island, Illinois 61299-7300. Commercial FAX 309-782-7609, or email birmingham@ria.army.mil
4. A letter of transmittal only shall be furnished to AMSTA-LC-CFA-B, ATTN: Mary Donovan or Rita Nelson, Commercial FAX 309-782-2301 or email donovanm@ria.army.mil or nelsonr@ria.army.mil.
5. The above procedure applies only to the lamp brightness requirements notes on the drawing.
6. All records of obtained actual data shall be available for audit by the Government.
7. The reviewing / approving office will notify the contractor by the next working day for approval to ship.

Other Drawing notes and requirements

All other drawing notes and requirements shall be complied with and certified via COC by the assembly producer.

All references to lamp illumination measurement data stated in accompanying QAPs are rescinded and replaced by the above requirements.